



**Haryana State Pollution Control Board**  
Gurgaon North Vikas Sada, 1st Floor, Near DC Court, Gurgaon Ph.  
0124-2332775



**BMW Annual Report Details**

**Application Id: 5123365**

| Particulars of the Occupier   |  |
|---|--|
| Annual report submit for year:  | 2017   |
| Name of the authorized person:  | KULDEEP SINGH PANWAR   |
| Name of HCF or CBMWTF:  | VULCAN WASTE MANAGEMENT PRIVATE LIMITED                                |
| Address for Correspondence:   | 1046, SECTOR-31  |
| Address of Facility:  | Damdama Road, Village Bhondsi, Tehsil Sohna, District Gurgaon, Haryana |
| Tel. No.:   | 9818586688   |
| Fax. No.:   | 00 - 00  |
| E-mail ID:  | kuldeepksp@gmail.com   |
| URL of Website:   |  |
| GPS coordinates of HCF of CBMWTF:                                     |  |
| Ownership of HCF or CBMWTF:   | Private  |
| Status of Authorization under the BMW (Management and Handing) Rules: |  |
| Authorization No.:  | HSPCB/EE/BMW6708   |
| Valid Upto:   | 31/03/2018   |
| Status of Consents under Water Act and Air Act.:                      |  |
| Valid Upto:   | 30/09/2020   |

| Health Care Facilities Details                       |        |
|--|--------|
| HCF/CBMWTF Type:                                     | CBMWTF |
| Number healthcare facilities covered by CBMWTF:      | 930    |
| No. of beds covered by CBMWTF:                       | 8246   |
| Installed treatment and disposal capacity of CBMWTF: | 7000   |
| Quantity of BMW treated or disposal by CBMWTF:       | 4384   |

| Quantity of Waste Generated  |       |
|--|-------|
| Quantity of waste generated or disposed in Kg per annum (on monthly average basis) |       |
| Yellow Category:   | 55298 |
| Red Category:  | 63600 |
| White Category:  | 1440  |
| Blue Category:   | 13048 |
| General Solid Waste:   | 0     |

| <b>Storage, Treatment, Transportation, Processing and Disposal Facility Details</b>         |                     |
|---|---------------------|
| Quantity of recyclable wastes sold to authorized recyclers after treatment in kg per annum: | 51357               |
| No of vehicles used for collection and transportation of BMW:                               | 13                  |
| Name of the Common BMW Treatment Facility Operator through which wastes are disposed of:    | Self                |
| Details of the on-site storage facility:  |                     |
| Size:   | 1 Acer              |
| Capacity:   | 7000 Kg             |
| Provision of on-site storage:   | 2 Rooms of 20*20 FT |

| <b>Disposal Facility</b>             |                 |                  |  |
|--------------------------------------|-----------------|------------------|--|
| Type of Treatment Equipment          | Number of Units | Capacity(Kg/day) | Quantity Treated or Disposed(Kg/annum) |
| Incinerators                         | 1               | 3000             | 663585                                 |
| Autoclaves                           | 1               | 4000             | 763202                                 |
| Shredder                             | 1               | 5000             | 648721                                 |
| Sharps encapsulation or concrete pit | 1               | 150              | 1440                                   |

| <b>Details of incineration, ash and ETP sludge generated, disposal during the treatment of wastes in Kg per annum</b> |                    |                |
|---|--------------------|----------------|
| Type of waste   | Quantity Generated | Where disposal |
| Ash   | 142350             | Gepil          |
| ETP Sludge  | 730                | Gepil          |

| <b>BMW Management Committee</b>       |    |
|---------------------------------------|----|
| Do you have BMW management committee: | no |

| <b>Training Conducted on BMW Details</b>               |     |
|--|-----|
| Number of training conducted on BMW Management:        | 10  |
| Number of personnel trained:                           | 42  |
| Number of personnel trained at the time of induction:  | 15  |
| Number of personnel not undergone any training so far: | 0   |
| Whether standard manual for training is available:     | yes |
| Any other information:                                 | NA  |

| <b>Details of the accident occurred</b> |    |
|---|----|
| No. of accident occurred:               | 0  |
| Number of the persons affected:         | 0  |
| Remedial Action taken:                  | NA |
| Any Fatality occurred, details:         | No |

| <b>Other Details</b>  |                                |
|---|--------------------------------|
| <b>Are you meeting the standards of air Pollution from the incinerator?. How many times in last year could not met the standards?:</b>      | Yes,N0                         |
| <b>Details of Continuous online emission monitoring systems installed:</b>  | Yes                            |
| <b>Liquid waste generated and treatment methods in place. How many times you have not met the standards in a year:</b>                      | ETP Provided ,NIL              |
| <b>It the disinfection method or sterilization meeting the log for standards? How many times you have not met the standards in a year?:</b> | Yes,Nil                        |
| <b>Any other relevant information:</b>  | APCD Attached with Incinerator |